



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
ROBERTSON DRIVE	o/s 5	Damaging	TR: Felling - Damage to Structures - Tree root has damaged boundary wall - Footway requires excavation prior to stump grind -	Prunus serrulata	o/s 5 - Pit	Malus 'Rudolph' - o/s 5
ROBERTSON DRIVE	o/s 17-19	Damaging	TR: Felling- - Extensive rooting within c/w, will be severed upon road surfacing + unable to repair without root(tree) removal	Acer platanoides	Plant in new 800mm pit o/s 17-19, (same as felled tree)	Malus 'Rudolph'
ROBERTSON DRIVE	o/s 18	Dead	TR: Felling- - Dead	Prunus serrulata	Plant in new 800mm pit o/s 18, (same as felled tree)	Malus 'Rudolph'